



RINGKASAN EKSEKUTIF

JADUAL PERTAMA PENILAIAN KESAN TERHADAP ALAM SEKELILING (EIA)										Penggerak Projek		Jururunding EIA																																																							
Proposed 33 kV Underground Cable Installation from Cable Landing Point (CLP) to Interconnection Facility (IF) at Remen Chereh Forest Reserve, Mukim Ulu Kuantan, District of Kuantan, Pahang										Chereh Solar Sdn. Bhd.		EnviroSolutions & Consulting Sdn. Bhd.																																																							
Pengenalan - Terletak di Hutan Simpan Remen Chereh, Empangan Chereh - Panjang Kabel: 1.6 km - Luas Kawasan Sambungan: 6 ha - Zon: Hutan			Lokasi Projek 			Deskripsi Projek - Konsep: Pemasangan 33 kV kabel atas dan bawah tanah, fasiliti sambungan dan talian penghantaran - Komponen: 1.6 km 33kV kabel merangkumi pemasangan <i>cable tray</i> atas tanah dan <i>trench</i> bawah tanah. - Pembinaan fasiliti sambungan melibatkan elemen mekanikal dan elektrik. - Empat (4) 275kV talian penghantaran.			Aktiviti Projek <table><tr><th>Pra-Pembinaan</th><th>Pembinaan</th><th>Operasi</th></tr><tr><td>Survei tapak Kajian penyelidikan tanah Kajian alam sekitar</td><td>Penyediaan tapak Kerja tanah <i>Piling & foundation</i> Jalan & Perparitan Kerja elektrik dan mekanikal</td><td>Pengoperasian kabel dan fasiliti sambungan</td></tr></table>			Pra-Pembinaan	Pembinaan	Operasi	Survei tapak Kajian penyelidikan tanah Kajian alam sekitar	Penyediaan tapak Kerja tanah <i>Piling & foundation</i> Jalan & Perparitan Kerja elektrik dan mekanikal	Pengoperasian kabel dan fasiliti sambungan																																																		
Pra-Pembinaan	Pembinaan	Operasi																																																																	
Survei tapak Kajian penyelidikan tanah Kajian alam sekitar	Penyediaan tapak Kerja tanah <i>Piling & foundation</i> Jalan & Perparitan Kerja elektrik dan mekanikal	Pengoperasian kabel dan fasiliti sambungan																																																																	
Keperluan Undang-Undang Aktiviti 11: Pembangunan talian penghantaran di Kawasan sensitif alam sekitar																																																																			
Keperluan Projek Menyokong penjanaan elektrik dari Projek Solar Terapung Chereh																																																																			
Alam Sekitar Sedia Ada  Beralun dengan ketinggian 50 – 180 meter  Indeks Kualiti Air: Kelas II  Kualiti udara mematuhi piawai  Bunyi bising dalam tahap dibenarkan  Majoriti bersetuju dengan Pembangunan Projek, yang terletak jauh dari perumahan  Terletak dalam HS Remen Chereh, bagaimanapun telah terdedah kepada elemen antropogenik										<table><tr><th>Impak</th><th>Pembinaan</th><th>Operasi</th><th>Langkah Mitigasi Utama</th></tr><tr><td>Hakisan Tanah</td><td>-</td><td></td><td> - Pemasangan kawalan hakisan yang betul - Pemantauan BMPs yang kerap - Memastikan zon penampungan sungai dikekalkan. </td></tr><tr><td>Kemerosotan Kualiti Air</td><td>-</td><td></td><td></td></tr><tr><td>Kualiti Udara</td><td>-</td><td></td><td> - Penyelenggaraan berkala jentera berat. </td></tr><tr><td>Bunyi Bising</td><td>-</td><td></td><td> - Mengehadkan halaju kenderaan berat. </td></tr><tr><td>Sosio Ekonomi</td><td>-</td><td></td><td> - Memastikan jalan awam yang digunakan sentiasa dalam keadaan baik. </td></tr><tr><td>Flora dan Fauna</td><td>-</td><td></td><td> - Mengehadkan kerja di Kawasan yang dibangunkan sahaja. </td></tr><tr><td></td><td>Rendah</td><td>Sederhana</td><td>Tinggi</td><td>Tidak Ketara</td><td>+ bererti Positif - bererti Negatif</td></tr></table>			Impak	Pembinaan	Operasi	Langkah Mitigasi Utama	Hakisan Tanah	-		- Pemasangan kawalan hakisan yang betul - Pemantauan BMPs yang kerap - Memastikan zon penampungan sungai dikekalkan.	Kemerosotan Kualiti Air	-			Kualiti Udara	-		Penyelenggaraan berkala jentera berat.	Bunyi Bising	-		Mengehadkan halaju kenderaan berat.	Sosio Ekonomi	-		Memastikan jalan awam yang digunakan sentiasa dalam keadaan baik.	Flora dan Fauna	-		Mengehadkan kerja di Kawasan yang dibangunkan sahaja.		Rendah	Sederhana	Tinggi	Tidak Ketara	+ bererti Positif - bererti Negatif	<table><tr><th>Pemantauan</th><th>Frekuensi</th><th>Parameter</th></tr><tr><td>Kolam Perangkap Mendap</td><td>Selepas hujan ≥12.5 mm</td><td>Pepejal terampai Kekeruhan</td></tr><tr><td>Kualiti Air</td><td>Bulanan</td><td>Table 6-4 dalam EIA</td></tr><tr><td>Kualiti Udara</td><td>Bulanan</td><td>Table 6-7 dalam EIA</td></tr><tr><td>Bunyi Bising</td><td>Setiap 3 Bulan</td><td>Laeq, Lmin, Lmax, L10, L90</td></tr><tr><td>BMPs</td><td>Selepas hujan</td><td>Keberkesanan</td></tr></table>			Pemantauan	Frekuensi	Parameter	Kolam Perangkap Mendap	Selepas hujan ≥12.5 mm	Pepejal terampai Kekeruhan	Kualiti Air	Bulanan	Table 6-4 dalam EIA	Kualiti Udara	Bulanan	Table 6-7 dalam EIA	Bunyi Bising	Setiap 3 Bulan	Laeq, Lmin, Lmax, L10, L90	BMPs	Selepas hujan	Keberkesanan
Impak	Pembinaan	Operasi	Langkah Mitigasi Utama																																																																
Hakisan Tanah	-		- Pemasangan kawalan hakisan yang betul - Pemantauan BMPs yang kerap - Memastikan zon penampungan sungai dikekalkan.																																																																
Kemerosotan Kualiti Air	-																																																																		
Kualiti Udara	-		Penyelenggaraan berkala jentera berat.																																																																
Bunyi Bising	-		Mengehadkan halaju kenderaan berat.																																																																
Sosio Ekonomi	-		Memastikan jalan awam yang digunakan sentiasa dalam keadaan baik.																																																																
Flora dan Fauna	-		Mengehadkan kerja di Kawasan yang dibangunkan sahaja.																																																																
	Rendah	Sederhana	Tinggi	Tidak Ketara	+ bererti Positif - bererti Negatif																																																														
Pemantauan	Frekuensi	Parameter																																																																	
Kolam Perangkap Mendap	Selepas hujan ≥12.5 mm	Pepejal terampai Kekeruhan																																																																	
Kualiti Air	Bulanan	Table 6-4 dalam EIA																																																																	
Kualiti Udara	Bulanan	Table 6-7 dalam EIA																																																																	
Bunyi Bising	Setiap 3 Bulan	Laeq, Lmin, Lmax, L10, L90																																																																	
BMPs	Selepas hujan	Keberkesanan																																																																	

EXECUTIVE SUMMARY

FIRST SCHEDULE ENVIRONMENTAL IMPACT ASSESSMENT (EIA)										Project Proponent		Environmental Consultant																																																																										
Proposed 33 kV Underground Cable Installation from Cable Landing Point (CLP) to Interconnection Facility (IF) at Remen Chereh Forest Reserve, Mukim Ulu Kuantan, District of Kuantan, Pahang										Chereh Solar Sdn. Bhd.		EnviroSolutions & Consulting Sdn. Bhd.																																																																										
Introduction - Located at Remen Chereh Forest Reserve - Cable Length: 1.6 km - IF area: 6 ha - Zoning: Forest			Legal Requirement Activity 11: Development of transmission line within environmental sensitive area			Needs Requirement Support electrical power generation by the floating solar Project.			Existing Environment  Undulating with ground level of 50 – 180 m  River WQI: Class II  Air quality complies with the standard  Noise level within stipulated limit  Majority of respondents agree with the Project as it located further from the residential area  Located within Remen Chereh FR, however, has been exposed to anthropogenic elements			Project Location 			Project Description - Concept: Installation of 33 kV cable above and under ground, IF and transmission tower - Components: 1.6 km 33kV cable using cable tray cable aboveground and trenches underground. - Construction of IF comprising of mechanical and electrical elements. - Four (4) 275kV transmission towers.			Project Activities <table><tr><th>Pre-construction</th><th>Construction</th><th>Operation</th></tr><tr><td>Site survey SI study Environmental study</td><td>Site preparation Earthworks Piling & foundation Road & drainage Electrical and Mechanical</td><td>Operation of cable and IF</td></tr></table>			Pre-construction	Construction	Operation	Site survey SI study Environmental study	Site preparation Earthworks Piling & foundation Road & drainage Electrical and Mechanical	Operation of cable and IF																																																												
Pre-construction	Construction	Operation																																																																																				
Site survey SI study Environmental study	Site preparation Earthworks Piling & foundation Road & drainage Electrical and Mechanical	Operation of cable and IF																																																																																				
<table><tr><th>Impact</th><th colspan="2">Construction</th><th colspan="2">Operation</th><th colspan="2">Main Mitigation Measure</th></tr><tr><td>Soil Erosion</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"> - Installation of erosion control measures - Frequent inspection of BMPs - Ensure that riparian buffer zones are maintained </td></tr><tr><td>Deterioration of Water Quality</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"></td></tr><tr><td>Air Quality</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"> - Maintenance of heavy vehicles regularly </td></tr><tr><td>Noise</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"> - Limit heavy vehicles speed </td></tr><tr><td>Socio Economy</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"> - Ensure that public roads used are well serviced </td></tr><tr><td>Flora and Fauna</td><td colspan="2">-</td><td colspan="2"></td><td colspan="2"> - Limit work only at areas within Project footprint. </td></tr><tr><td></td><td>Low</td><td>Moderate</td><td>High</td><td>Not significant</td><td colspan="2">+ means Positive - means Negative</td></tr></table>										Impact	Construction		Operation		Main Mitigation Measure		Soil Erosion	-				- Installation of erosion control measures - Frequent inspection of BMPs - Ensure that riparian buffer zones are maintained		Deterioration of Water Quality	-						Air Quality	-				Maintenance of heavy vehicles regularly		Noise	-				Limit heavy vehicles speed		Socio Economy	-				Ensure that public roads used are well serviced		Flora and Fauna	-				Limit work only at areas within Project footprint.			Low	Moderate	High	Not significant	+ means Positive - means Negative		<table><tr><th>Monitoring</th><th>Frequency</th><th>Parameters</th></tr><tr><td>Sediment basin</td><td>After rainfall ≥12.5 mm</td><td>TSS Turbidity</td></tr><tr><td>Water Quality</td><td>Monthly</td><td>Table 6-4 of the EIA</td></tr><tr><td>Air Quality</td><td>Monthly</td><td>Table 6-7 of the EIA</td></tr><tr><td>Noise Level</td><td>Quarterly</td><td>Laeq, Lmin, Lmax, L10, L90</td></tr><tr><td>BMPs</td><td>After rainfall event</td><td>Effectiveness</td></tr></table>			Monitoring	Frequency	Parameters	Sediment basin	After rainfall ≥12.5 mm	TSS Turbidity	Water Quality	Monthly	Table 6-4 of the EIA	Air Quality	Monthly	Table 6-7 of the EIA	Noise Level	Quarterly	Laeq, Lmin, Lmax, L10, L90	BMPs	After rainfall event	Effectiveness
Impact	Construction		Operation		Main Mitigation Measure																																																																																	
Soil Erosion	-				- Installation of erosion control measures - Frequent inspection of BMPs - Ensure that riparian buffer zones are maintained																																																																																	
Deterioration of Water Quality	-																																																																																					
Air Quality	-				Maintenance of heavy vehicles regularly																																																																																	
Noise	-				Limit heavy vehicles speed																																																																																	
Socio Economy	-				Ensure that public roads used are well serviced																																																																																	
Flora and Fauna	-				Limit work only at areas within Project footprint.																																																																																	
	Low	Moderate	High	Not significant	+ means Positive - means Negative																																																																																	
Monitoring	Frequency	Parameters																																																																																				
Sediment basin	After rainfall ≥12.5 mm	TSS Turbidity																																																																																				
Water Quality	Monthly	Table 6-4 of the EIA																																																																																				
Air Quality	Monthly	Table 6-7 of the EIA																																																																																				
Noise Level	Quarterly	Laeq, Lmin, Lmax, L10, L90																																																																																				
BMPs	After rainfall event	Effectiveness																																																																																				